TABLE *of* CONTENTS

1. EXECUTIVE SUMMARY & INTRODUCTION...1-1
- 1.1 Executive Summary ...1-1
- 1.2 Introduction ...1-3
  - 1.2.1. Background ... 1-3
  - 1.2.2. Public Concerns and Issues ... 1-3
  - 1.2.3. Scope of Project & Project Objectives ...1-3

2. SETTING ...2-1
- 2.1. Regional Setting...2-1
- 2.2. Natural History ...2-1
  - 2.2.1. Geology ...2-1
  - 2.2.2. Hydrology ...2-3
  - 2.2.3. Biology ...2-3
- 2.3. Historic and Present Watershed Boundaries ...2-6
- 2.4. Jurisdictional Boundaries ...2-6
- 2.5. Land Use ...2-6

3. LAGOON AND WATERSHED HISTORY ...3-1
- 3.1. Historic Drainage and Morphology ...3-1
  - 3.1.1. Lagoon Hydrology Prior to Yacht Harbor and Coastal Development ...3-1
  - 3.1.2. Watershed Hydrology and Drainage System ...3-4
- 3.2. Current Drainage and Morphology ...3-4
  - 3.2.1. Lagoon Hydrology ...3-4
  - 3.2.2. Watershed Modifications and Hydrology ...3-11
- 3.3. Summary and Conclusions ...3-16

4. WATER QUALITY...4-1
- 4.1. Overview ...4-1
- 4.2. Review of Historical Water Quality Studies and Monitoring Activities ...4-2
- 4.3. Water Quality Monitoring ...4-4
  - 4.3.1 Methodology ...4-5
  - 4.3.2 Results and Field Observations ...4-7
- 4.4. Summary of Findings ...4-37

5. RESTORATION OPTIONS...5-1
- 5.1. Lagoon Restoration and Education Opportunities ...5-1
  - 5.1.1. Improve Lagoon Water Circulation ...5-1
  - 5.1.2. Create Wetlands in Upper Lagoon ...5-6
  - 5.1.3. Reshape Bank Slopes and Restore Lagoon Fringe Wetlands ...5-8
  - 5.1.4. Remove Non-Native Plants and Restore with Native Wetland and Upland Species ...5-10

5.1.5. Interpretive Trail and Signing……5-11
5.2. Watershed Restoration Options ……5-12
5.2.1. Water Treatment Wetland at 38th Ave. Detention Basin …5-12
5.2.2 Restore Moran Creek Riparian Corridor ……5-13
5.3. Storm Water Management and Treatment ……5-15
5.3.1 Innovative Sight Design ……5-15
5.3.2. Storm Water Control and Treatment BMPs ……5-16
5.3.3. Performance Standards for Storm Water Management …5-16
5.4. Public Education and Outreach ……5-28

6. IMPLEMENTATION ……. 6-1
6.1. Planning and Implementation …… 6-1
6.1.1 Funding …… 6-1
6.1.2. Restoration Project Implementation…… 6-1
6.1.3. Public Education and Programmatic Activities ……. 6-2
6.2 Project Cost Analysis …… 6-3
6.2.1. Replacement of the East Cliff Drive Box Culvert with an Arched, Bottomless Culvert …….. 6-4
6.2.2. Upper Lagoon Wetland ……. 6-6
6.2.3. Reshape and Stabilize Lagoon Bank ……. 6-7
6.2.4. Modify 38th Avenue Detention Basin with a Low-flow Wetland ……. 6-8
6.2.5. Restore Moran Creek Corridor ……. 6-9
6.2.6. Removal of Non-native Invasive Plants and Revegetation with Natives ……. 6-10
6.2.7. Intrepretative Signs …… 6-10
6.3 Constraint Analysis …….. 6-10

7. REFERENCES …….……..……. 7-1

APPENDIX A—STORMWATER BEST MANAGEMENT PRACTICES (BMP'S)

LIST OF FIGURES

Figure 2.1. Vicinity Map of Moran Lake - Santa Cruz County

Figure 2.2. Pre and Post Development Watershed Areas - Moran Lake

Figure 2.3. Moran Lake Jurisdictional Boundaries

Figure 2.4. Arial photo of Moran Lake taken April 1, 1931

Figure 2.5. Arial photo of Moran Lake taken August 23, 1953

Figure 2.6. Arial photo of Moran Lake taken March 26, 1986

Figure 3.1. Moran Lake Beach Profile, 2001-2002 Season

Figure 3.2. Summary of Conductivity and Salinity Measurements Collected During the First Flush Event on October 31, 2003 from Site 2

Figure 3.3 Moran Lake After Ephemeral Bar has Breached and Lagoon is Partially Mixed – November 12, 2003

Figure 3.4. Moran Lake Beach After Ephemeral Bar has Breached and Lagoon is Partially Mixed – *November 12, 2003*

Figure 3.5. Lagoon Outflow Non-Stratified with Primarily Freshwater Flow – *February 2, 2004*

Figure 3.6. Moran Lake when the Lagoon is Non-Stratified with Primarily Freshwater Flow – *February 2, 2004*

Figure 3.7. Algal Blooms on the Surface of Moran Lake when the Lagoon is Non-Stratified with Little or No Flow from Freshwater or Tidal Inputs – *October 28, 2003*

Figure 3.8. Moran Lake when the Lagoon is Non-Stratified with Little or No Flow from Freshwater or Tidal Inputs and the Lagoon is Primarily Filled with Saline Water– *October 28, 2003*

Figure 3.9. Moran Lake Box Culvert Closed with Sand– *October 28, 2003*

Figure 3.10. Moran Creek

Figure 3.11. 38th Avenue Stormwater Basin

Figure 3.12. Changes in Watershed Hydrology as a Result of Urbanization

LIST OF FIGURES CONTINUED:

Figure 3.13. Channel Erosion in Upper Reach of Moran Lake

Figure 4.1. Moran Lake Sampling Locations

Figure 4.2. Sampling Location #4, Moran Creek East of 30th Avenue

Figure 4.3. pH in Moran Lake (June 26, 2003 to October 31, 2003)

Figure 4.4.1. Dissolved Oxygen Concentrations at Lagoon Inlet (Site 1)

Figure 4.4.2. Dissolved Oxygen Concentrations at Site 2

Figure 4.4.3. Dissolved Oxygen Concentration at Site 3

Figure 4.4.4. Dissolved Oxygen Concentration in Moran Creek

Figure 4.5. Morning and Afternoon Dissolved Oxygen Concentrations

Figure 4.6. Water Temperature (Degrees ^{o}C) Measured at Sites 1 and Site 4

Figure 4.7. Nutrient Concentrations at Site 2 on October 28 and October 31, 2003

Figure 4.8. Results of Fecal Coliform Counts on August 12 and October 31, 2003

Figure 4.9. Total Suspended Solids Concentrations

Figure 4.10. Turbidity Measurements taken on August 12th and October 31st 2003

Figure 4.11. Salinity Measurements Collected at Site 1

Figure 4.12. Salinity Measurements on June 5th, July 25th, September 30th, 2003

Figure 4.13. Salinity and Conductivity Measurements at Site 2 on October 31, 2003.

Figure 5.1. Moran Lake Outlet (September, 2002)

Figure 5.2. Corcoran Lagoon (September, 2002)

Figure 5.3. Examples of Bottomless Arched Culvert Crossings

Figure 5.4. Public Land in Upper Lagoon Identified for Possible Wetland Development

LIST OF FIGURES CONTINUED:

Figure 5.5. Conceptual Layout of Proposed Wetland in the Upper Lagoon Area of Moran Lake

Figure 5.6. Cross-Section of Restored Wetland Area

Figure 5.7. Eroding Bank on the Eastern Shore of Moran Lake

Figure 5.8. Cross-Section showing the Conceptual Layout of Restored Bank on Eastern Shore of Moran Lake

Figure 5.9. Possible Location for Revegetation with Native Plant Species

Figure 5.10. Example of Interpretive Sign

Figure 5.11. Conceptual Layout of 38th Avenue Detention Basin Modified to Include a Stormwater Wetland

Figure 5.12. Conceptual Layout of Moran Creek Stream Restoration

LIST OF TABLES

Table 4.1. pH Field Measurements

Table 4.2. Dissolved Oxygen Concentration (mg/L) Measurements

Table 4.3. Temperature Field Measurements (Degrees Centrigrade, ^{o}C)

Table 4.4. Nutrient (Nitrogen and Phosphorus) Measurements (in mg/L)

Table 4.5. Total and Fecal Coliform Measurements

Table 4.6. Turbidity (in NTU) and Total Suspended Solids (in mg/L) Measurements

Table 4.7. Salinity Field Measures (in parts per thousand, ppt)

Table 4.8. Conductivity Field Measurements (in micron siemens, mS)

Table 4.9. General Mineral Analysis

Table 4.10. Total Copper, Lead and Zinc Concentrations (all in units ug/L)

Table 4.11. California Toxics Rule (US EPA Water Quality Criteria) for the Protection of Freshwater and Saltwater Aquatic Life

Table 4.12. Water Quality Objectives from the Central Coast Region Water Quality Control Plan

Table 4.13. Comparison of Moran Creek and Lagoon Water Quality to Urban Runoff Water Quality in Other Areas

Table 4.14. Sediment Quality Test Results - November 25, 2003

Table 4.15. Comparison of Moran Lake Sediment Quality to Other Areas

Table 6.1. Preliminary Cost Estimate for Arched Bottomless Culvert for East Cliff Drive Crossiong

Table 6.2. Preliminary Cost Estimate for Wetland in Upper Lagoon

Table 6.3. Preliminary Cost Estimate for Bank Stabilization Project on east side of Lagoon

Table 6.4. Preliminary Cost Estimate to Modify 38th Avenue Detention Basin with a Low-Flow Wetland

Table 6.5. Preliminary Cost Estimate for 1000 feet of Channel Restoration

Table 6.6. Cost Estimate for Non-Native Plant Removal and Revegetation

Table 6.7. Costs for Interpretative Signs and Trails

Table 6.8. Benefits and Constraints Analysis